



CONDITION REPORT

2019 OPEL COMBO COMBO 1.6 TD 74KW EXPRESS 650KG
S/S SWB 100HP

2019 | 40937 KM | Manual | Diesel | 100 hp

Seller Disclosure



2096LDB

Engine Size	1560 cm3
Seats	-
Number of Doors	3
Body Style	-
Body Colour	BLANCO
HP	100 hp
VIN	W0VEFYHYCLN500716
Technical Inspection	
DUA	No
Registration Date	05/12/2019
Last Service Date	-
2º CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assessment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -