



CONDITION REPORT

2024 BMW i7 M70 xDrive Berlina (G70) i7 M70 xDrive Berlina (G70) 485HP

2024 | 5658 KM | auto | electric | 485 kw

Seller Disclosure




7724MPW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Frozen Pure
HP	485 kw
VIN	WBY81EH070CR77604
Technical Inspection	
DUA	No
Registration Date	23/04/2024
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	




Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location Auction Centre - Manheim Directo, S.L.U.


Inspection
Location Auction Centre - Manheim Directo, S.L.U.




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -