



CONDITION REPORT

2024 BMW 330e xDrive Touring (G21) 330e xDrive Touring (G21) 215HP

2024 | 18688 KM | auto | Petrol | 215 kw

Seller Disclosure



4061MRL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Skyscraper Grau metalizado
HP	215 kw
VIN	WBA71CY070FS31795
Technical Inspection	
DUA	No
Registration Date	17/05/2024
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
EQUIPAMIENTO:


ACC.CONF ; ASI.CAL ; ASI.DEP ;
ASI.DEP ; ASI.MEM ; Park Assist. ;
ASIST.LUZ CARRET. ; AUT LEVAS ; CC ;
Driv.Asist. ; HIFI ; LED ; PAQ.M ; PAQ.M*
; PAQ.M* ; Volante M

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -