



CONDITION REPORT

2024 BMW 420d Gran Coupé (G26) 420d Gran Coupé (G26)
140HP

2024 | 26554 KM | auto | Diesel | 140 kw

Seller Disclosure



2078MSD

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	black
HP	140 kw
VIN	WBA21AX050FT37436
Technical Inspection	
DUA	No
Registration Date	13/06/2024
Last Service Date	-
2 ^e CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT


EQUIPAMIENTO:
; ACC.CONF ;
ASI.CAL ; ASI.MEM ; Park Assist. ;
ASIST.LUZ CARRET. ; AUT LEVAS ; CC
ACT ; D.Dep ; Driv.Asist. ; Mild-Hybrid 48V
; PAQ.M ; PAQ.M* ; PAQ.M* ; SUSP. M ;
Volante M

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -