



CONDITION REPORT

2021 Nissan E-NV200 Nissan e-NV200 Furgón 4p 40 kWh
PROFESIONAL furgón HP

2021 | 56114 KM | auto | electric |

Seller Disclosure



9133LNG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Iceberg Blanco sólido
HP	-
VIN	VSKHAAME0U0620846
Technical Inspection	
DUA	No
Registration Date	24/03/2021
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -