



CONDITION REPORT

2021 TOYOTA PROACE PROACE 1.5D 100CV GX 1PL 2PT L1 HP

2021 | 86654 KM | Manual | Diesel |

Seller Disclosure



4530LSW

Engine Size	1499 cm3
Seats	-
Number of Doors	4
Body Style	-
Body Colour	- BLANCO ARCTIC
HP	-
VIN	YARVBYHRKGZ005057
Technical Inspection	
DUA	No
Registration Date	17/09/2021
Last Service Date	-

- 2º CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN (Informe Técnico) PARA MÁS FOTOS + COMPROBAR POSIBLES DAÑOS + INFORMACIÓN ADICIONAL

Location	Madrid
Auction Centre	Madrid

Inspection

Location	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -