



CONDITION REPORT

2022 BMW 118d (F40) 118d (F40) 110HP

2022 | 55633 KM | auto | Diesel | 110 kw

Seller Disclosure



8536LVW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	110 kw
VIN	WBA7M910707K49065
Technical Inspection	
DUA	No
Registration Date	13/01/2022
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes

DOCUMENTACION EN CUSTODIA DE
GESTORIA
EQUIPAMIENTO:
;
ACC.CONF ; AUT ; CC ; LED ;
PAQ.Business ; PDC

Inspection

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -