



CONDITION REPORT

2020 BMW M850i xDrive Gran Coupé (G16) M850i xDrive
Gran Coupé (G16) 390HP

2020 | 116598 KM | auto | Petrol | 390 kw

Seller Disclosure



2561LHM

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	390 kw
VIN	WBAGV81060CE71209
Technical Inspection	
DUA	No
Registration Date	10/07/2020
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Location

Auction Centre

-

Madrid

Inspection


Location

Auction Centre


-

Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -