



CONDITION REPORT

2020 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2020 | 91088 KM | auto | electric | 125 kw

Seller Disclosure



8221LHR

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralgrau con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210507F90715
Technical Inspection	
DUA	No
Registration Date	17/07/2020
Last Service Date	-








-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment

 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -