



CONDITION REPORT

2024 BMW 116d (F40) 116d (F40) 85HP

2024 | 17723 KM | Manual | Diesel | 85 kw

Seller Disclosure



0211MMV

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	M Misano Blue metallic
HP	85 kw
VIN	WBA7M710307N42272
Technical Inspection	
DUA	No
Registration Date	18/01/2024
Last Service Date	-


-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen




Equipment	Public Notes	Inspection
	POSIBILIDAD EXTRAVIO FT CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid


Damage Assesment




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-




Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-



Damage Detail :-
Damage Type :-
Damage Size :-