



CONDITION REPORT

2021 BMW X1 sDrive18i (F48) X1 sDrive18i (F48) 103HP
2021 | 104916 KM | Manual | Petrol | 103 kw
Seller Disclosure



1098LTG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	white
HP	103 kw
VIN	WBA31AA0X05U06799
Technical Inspection	
DUA	No
Registration Date	08/10/2021
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT

EQUIPAMIENTO:
; ASIST.APARC ;
CC ; LED ; NAV* ; PAQ.Business ; PDC ;
Perform.Ctrl

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -