



CONDITION REPORT

2020 DS DS 3 CROSSBACK BlueHdi 73 kW Manual SO CHIC
100HP

2020 | 88905 KM | Manual | Diesel | 100 hp

Seller Disclosure



0664LLG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VR1UCYHYJLW024257
Technical Inspection	
DUA	No
Registration Date	26/11/2020
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -