



CONDITION REPORT

2020 Jaguar E-PACE 2 E-PACE 2.0D 110kW HP

2020 | 123823 KM | Manual | Diesel |

Seller Disclosure



3253LGC

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	-
HP	-
VIN	SADFB2DN1L1Z82937
Technical Inspection	
DUA	No
Registration Date	09/03/2020
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes


Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Técnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL


Location Madrid
Auction Centre Madrid

Inspection

Location Madrid
Auction Centre Madrid



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -