



CONDITION REPORT

2020 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2020 | 85093 KM | auto | electric | 125 kw

Seller Disclosure



8033LJT

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralgrau con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210807F69647
Technical Inspection	
DUA	No
Registration Date	10/09/2020
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -