



CONDITION REPORT

2019 DS DS 3 CROSSBACK BlueHdi 73 kW Manual SO CHIC
100HP

2019 | 88993 KM | Manual | Diesel | 100 hp

Seller Disclosure



2501LDH

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VR1UCYHYJKW132739
Technical Inspection	
DUA	No
Registration Date	19/12/2019
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Location	Madrid
Auction Centre	Madrid

Inspection

Location	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -