



CONDITION REPORT

2019 Volkswagen CADDY Profesional Furgon 1.4 TGI 81kW
BM 110HP

2019 | 1 KM | Manual | lpg | 110 hp

Seller Disclosure



9015KZV

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco candy sÃ³lido
HP	110 hp
VIN	WV1ZZZ2KZKX135612
Technical Inspection	
DUA	No
Registration Date	29/08/2019
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location Madrid
Auction Centre Madrid


Inspection

Location Madrid
Auction Centre Madrid

Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -