



CONDITION REPORT

2018 Citroen Berlingo (O) Multispace LIVE Edit.BlueHDI
74KW (100CV 100HP)

2018 | 141074 KM | Manual | Diesel | 100 hp


Seller Disclosure



6475KSH

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VF77JBHY6JJ763890
Technical Inspection	
DUA	No
Registration Date	18/12/2018
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN (Informe Técnico) PARA COMPROBAR POSIBLES DAÑOS E INFORMACIÓN ADICIONAL

Location Madrid
Auction Centre Madrid

Inspection

Location Madrid
Auction Centre Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -