



CONDITION REPORT

2019 BMW X5 xDrive45e 394HP

2019 | 109710 KM | auto | hybrid | 394 hp

Seller Disclosure



4777LDN

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Arktikgrau
HP	394 hp
VIN	WBATA610209B18848
Technical Inspection	
DUA	No
Registration Date	27/12/2019
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Location	Madrid
Auction Centre	Madrid

Inspection

Location	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -