



CONDITION REPORT

2020 DS DS 7 CROSSBACK BlueHDi DE 96kW (130CV)
PERFORMANCE LINE todoterre HP

2020 | 77831 KM | Manual | Diesel |

Seller Disclosure



2848LDX

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco Banquise - POWP
HP	-
VIN	VR1JCYHZJKY225213
Technical Inspection	
DUA	No
Registration Date	17/01/2020
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -