



CONDITION REPORT

2021 BMW X4 xDrive20d (G02) X4 xDrive20d (G02) 140HP

2021 | 43184 KM | auto | Diesel | 140 kw

Seller Disclosure



7288LTB

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Sophistograu,efecto brillo metalizado
HP	140 kw
VIN	WBA4M910509H77665
Technical Inspection	
DUA	No
Registration Date	29/09/2021
Last Service Date	-
 2ª CHAVE	
 Service History	
 VAT	
 Sold as Seen	



Equipment	Public Notes	Inspection	
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location Auction Centre	Madrid-ES34 Madrid

Inspection	
Location	Madrid-ES34
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -