



CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON 1.6 CRDI 100KW 48V
STYLE DT 2WD 136HP

2020 | 92938 KM | Manual | | 136 hp

Seller Disclosure

9268LGK

Engine Size	1598 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	POLAR WHITE
HP	136 hp
VIN	TMAJ3817GLJ044804
Technical Inspection	
DUA	No
Registration Date	22/05/2020
Last Service Date	-

- ✗ 2º CHAVE
- ✗ Service History
- ✓ VAT
- ✗ Sold as Seen



Equipment

Public Notes

Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Location
Auction Centre

Inspection

Location
Auction Centre

-
Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -