



# CONDITION REPORT

2021 Citroen JUMPER Citroen Jumper BlueHDi 103KW  
(140CV) Furgón 35L3H2 HP

2021 | 104583 KM | Manual | Diesel |

Seller Disclosure



0041LSZ

|                      |                      |
|----------------------|----------------------|
| Engine Size          | -                    |
| Seats                | -                    |
| Number of Doors      | -                    |
| Body Style           | -                    |
| Body Colour          | Blanco Hielo (opaco) |
| HP                   | -                    |
| VIN                  | VF7YCBNFC12S94175    |
| Technical Inspection |                      |
| DUA                  | No                   |
| Registration Date    | 24/09/2021           |
| Last Service Date    | -                    |

- 2º CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA MÁS FOTOS +  
COMPROBAR POSIBLES DAÑOS +  
INFORMACIÓN ADICIONAL

Location -  
Auction Centre Madrid


Inspection

Location -  
Auction Centre Madrid

Damage Assesment



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -