



CONDITION REPORT

2020 BMW 116d (F40) 116d (F40) 85HP

2020 | 102369 KM | auto | Diesel | 85 kw

Seller Disclosure



5142LFX

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710007F22712
Technical Inspection	
DUA	No
Registration Date	28/02/2020
Last Service Date	-

-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection


POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Location Madrid-ES34
Auction Centre Madrid


Inspection

Location Madrid-ES34
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -