



CONDITION REPORT

2019 Renault TRAFIC Furgon 29 L1H1 Energy BluedCi 88 kW
120HP

2019 | 113763 KM | Manual | Diesel | 120 hp

Seller Disclosure



4259LCL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco casablanca (o
HP	120 hp
VIN	VF1FL000564306192
Technical Inspection	
DUA	No
Registration Date	14/11/2019
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -