



# CONDITION REPORT

2020 MERCEDES GLC-CLASS GLC 200 d 4MATIC 163HP

2020 | 56372 KM | auto | Diesel | 163 hp

Seller Disclosure



**6934LLF**

|                                                                                                       |                   |
|-------------------------------------------------------------------------------------------------------|-------------------|
| Engine Size                                                                                           | -                 |
| Seats                                                                                                 | -                 |
| Number of Doors                                                                                       | -                 |
| Body Style                                                                                            | -                 |
| Body Colour                                                                                           | Gris grafito      |
| HP                                                                                                    | 163 hp            |
| VIN                                                                                                   | W1N2539161V273718 |
| Technical Inspection                                                                                  |                   |
| DUA                                                                                                   | No                |
| Registration Date                                                                                     | 03/12/2020        |
| Last Service Date                                                                                     | -                 |
|  2ª CHAVE         |                   |
|  Service History |                   |
|  VAT             |                   |
|  Sold as Seen    |                   |



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

Location -  
Auction Centre Madrid

Inspection

Location -  
Auction Centre Madrid

Damage Assesment



Damage Detail : -  
Damage Type : -  
Damage Size : -