



CONDITION REPORT

2019 Peugeot 308 5p Style BlueHDi 75KW (100CV) 100HP

2019 | 83767 KM | Manual | Diesel | 100 hp

Seller Disclosure



3379KXW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Gris platinun
HP	100 hp
VIN	VF3LBYHYPKS236370
Technical Inspection	
DUA	No
Registration Date	11/06/2019
Last Service Date	-
 2ª CHAVE	
 Service History	
 VAT	
 Sold as Seen	



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location	-
Auction Centre	Madrid

Inspection

Location	-
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -