



CONDITION REPORT

2022 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2022 | 26667 KM | auto | electric | 125 kw

Seller Disclosure



8411LWC

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Capparisweis con acentuación BMW i Blau
HP	125 kw
VIN	WBY8P210007K48425
Technical Inspection	
DUA	No
Registration Date	31/01/2022
Last Service Date	-

- 2º CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/8411LWC.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Location -
Auction Centre Manheim Directo,
S.L.U.


Inspection

Location -
Auction Centre Manheim Directo,
S.L.U.


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -