



CONDITION REPORT

2021 Peugeot 3008 Peugeot 3008 1.5 BlueHDi 96kW (130CV)
S&S Allure t HP

2021 | 146789 KM | Manual | Diesel |

Seller Disclosure



0883LNG

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco Nacarado (3 capas)
HP	-
VIN	VF3MCYHZMMS080261
Technical Inspection	
DUA	No
Registration Date	22/03/2021
Last Service Date	-

- 2ª CHAVE
- Service History
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Location	Madrid
Auction Centre	Madrid

Inspection

Location	Madrid
Auction Centre	Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -