



CONDITION REPORT

2020 Mini Cooper SE (F56) Cooper SE (F56) 135HP

2020 | 69732 KM | auto | electric | 135 kw

Seller Disclosure



4908LLW

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	White Silver
HP	135 kw
VIN	WMWXP310002N77820

Technical Inspection

DUA	No
Registration Date	23/12/2020
Last Service Date	-


-  2ª CHAVE
-  Service History
-  VAT
-  Sold as Seen




Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location Auction Centre - Manheim Directo, S.L.U.

Inspection
Location Auction Centre - Manheim Directo, S.L.U.


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -