



# CONDITION REPORT

**2021 BMW 116d (F40) 116d (F40) 85HP**

**2021 | 89125 KM | Manual | Diesel | 85 kw**

**Seller Disclosure**



**5817LNS**

|                                                                                                       |                   |
|-------------------------------------------------------------------------------------------------------|-------------------|
| Engine Size                                                                                           | -                 |
| Seats                                                                                                 | -                 |
| Number of Doors                                                                                       | -                 |
| Body Style                                                                                            | -                 |
| Body Colour                                                                                           | grey              |
| HP                                                                                                    | 85 kw             |
| VIN                                                                                                   | WBA7M710305T28233 |
| Technical Inspection                                                                                  |                   |
| DUA                                                                                                   | No                |
| Registration Date                                                                                     | 14/04/2021        |
| Last Service Date                                                                                     | -                 |
|  2ª CHAVE         |                   |
|  Service History |                   |
|  VAT             |                   |
|  Sold as Seen    |                   |



| Equipment | Public Notes                                                                                                                                                   | Inspection                                    |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
|           | DOCUMENTACION EN CUSTODIA DE GESTORIA<BR><a href="http://soportemanheim.es/E/5817LNS.htm" target="_blank">CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO</a><br> | <div>Location-<br/>Auction CentreMadrid</div> |

| Inspection                                    |
|-----------------------------------------------|
| <div>Location-<br/>Auction CentreMadrid</div> |

| Damage Assesment                                                                                                                                                                                                                                                                                                                            |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <div><div><div>Damage Detail : -<br/>Damage Type : -<br/>Damage Size : -</div></div><div><div>Damage Detail : -<br/>Damage Type : -<br/>Damage Size : -</div></div></div> |