



## CONDITION REPORT

**2019 Peugeot 308 BUSINESS LINE 1.2 PURETECH 81KW  
(110CV) 110HP**


**2019 | 109000 KM | Manual | Petrol | 110 hp**

**Seller Disclosure**



**9639KWX**

|                                                                                                       |                   |
|-------------------------------------------------------------------------------------------------------|-------------------|
| Engine Size                                                                                           | -                 |
| Seats                                                                                                 | -                 |
| Number of Doors                                                                                       | -                 |
| Body Style                                                                                            | -                 |
| Body Colour                                                                                           | Blanco blanquise  |
| HP                                                                                                    | 110 hp            |
| VIN                                                                                                   | VF3LPHNPTKS087788 |
| Technical Inspection                                                                                  |                   |
| DUA                                                                                                   | No                |
| Registration Date                                                                                     | 13/05/2019        |
| Last Service Date                                                                                     | -                 |
|  2ª CHAVE         |                   |
|  Service History |                   |
|  VAT             |                   |
|  Sold as Seen    |                   |



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

Location -  
Auction Centre Madrid

Inspection

Location -  
Auction Centre Madrid

Damage Assesment



Damage Detail : -  
Damage Type : -  
Damage Size : -