



CONDITION REPORT

2022 DS DS 3 CROSSBACK PureTech 73 kW Manual
PERFORMANCE LINE 100HP


2022 | 91841 KM | Manual | | 100 hp

Seller Disclosure



4583LWP

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco banquise
HP	100 hp
VIN	VR1URHNEKMW108879
Technical Inspection	
DUA	No
Registration Date	28/02/2022
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

IMPORTANTE: VER PERITACIÓN (Informe Técnico) PARA COMPROBAR POSIBLES DAÑOS E INFORMACIÓN ADICIONAL

Inspection

Location	-
Auction Centre	Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -