



CONDITION REPORT

2022 Citroen C3 BlueHDi 75KW (100CV) S&S Live Pack
102HP


2022 | 64936 KM | Manual | Diesel | 102 hp

Seller Disclosure



9980LXJ

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco banquise
HP	102 hp
VIN	VF7SXYHTUNT539335
Technical Inspection	
DUA	No
Registration Date	20/04/2022
Last Service Date	-
2ª CHAVE	
Service History	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -