# CONDITION REPORT

**2014 BMW Serie-5 LCI Diesel 520 d Pack M 190HP Saloon**

**2014 | 136496 KM | Manual | Diesel | 190 hp**

**Seller Disclosure**



**4 Grade Manheim**

**36-PG-37**

| | |
|---|---|
| **Engine Size** | 1995 cm3 |
| **Seats** | 5 |
| **Number of Doors** | 4 |
| **Body Style** | Saloon |
| **Body Colour** | Azul |
| **HP** | 190 hp |
| **VIN** | WBA5E51010G100244 |
| **Technical Inspection** | |
| **DUA** | Yes |
| **Registration Date** | 19/11/2014 |
| **Last Service Date** | Aos 132.330 kms em 27.03.2019 - digital |

- **2ª CHAVE**
- **Service History**
- **VAT**
- **Sold as Seen**

## Condition Info

| | |
|---|---|
| **Sold as Seen** | No |
| **Engine** | - |
| **Transmission** | - |
| **Suspension** | - |
| **Brakes** | - |
| **Clutch** | - |
| **Gearbox** | - |
| **Steering** | - |

## Equipment

XENON LAMPS
ALLOY WHEELS
PARKING AID
SECOND KEYS
SERVICE HISTORY
AUTO AIRCON

## Public Notes

VERIFIQUE PERITAGEM DENTRO DO ECR MANHEIM
KIT ANTIFURO EM FALTA
ULT REV Aos 132.330 kms em 27.03.2019 - digital
CUSTO AVERB 80€/
DEMORA APROX 30
VIATURA NÃO INSPECIONADA

## Inspection

| | |
|---|---|
| **Location** | - |
| **Auction Centre** | Lisboa |

## Damage Assesment



**Damage Detail :** Pára-brisas_frente+capot
**Damage Type :** Picado
**Damage Size :** Ver Imagem



**Damage Detail :** Pára-choques_frente
**Damage Type :** Raspado
**Damage Size :** Ver Imagem



**Damage Detail :** Retrovisor
**Damage Type :** Raspado
**Damage Size :** Ver Imagem



**Damage Detail :** Pára-choques_traseiro
**Damage Type :** Raspado
**Damage Size :** Ver Imagem



**Damage Detail :** Jantes
**Damage Type :** Raspadas
**Damage Size :** Ver Imagem