




CONDITION REPORT

2014 BMW Serie-5 LCI Diesel 520 d Pack M 190HP Saloon
2014 | 136496 KM | Manual | Diesel | 190 hp
Seller Disclosure



4

Grade
Manheim

36-PG-37

Engine Size	1995 cm3
Seats	5
Number of Doors	4
Body Style	Saloon
Body Colour	Azul
HP	190 hp
VIN	WBA5E51010G100244
Technical Inspection	
DUA	Yes
Registration Date	19/11/2014
Last Service Date	Aos 132.330 kms em 27.03.2019 - digital

- ✓ 2ª CHAVE
- ✓ Service History
- ✓ VAT
- ✗ Sold as Seen



Condition Info

Sold as Seen	No
Engine	-
Transmission	-
Suspension	-
Brakes	-
Clutch	-
Gearbox	-
Steering	-

Equipment

XENON LAMPS
 ALLOY WHEELS
 PARKING AID
 SECOND KEYS
 SERVICE HISTORY
 AUTO AIRCON


Public Notes

VERIFIQUE PERITAGEM DENTRO DO
 ECR MANHEIM
 KIT ANTIFURO EM FALTA
 ULT REV Aos 132.330 kms em
 27.03.2019 - digital
 CUSTO AVERB 80€/
 DEMORA APROX 30
 VIATURA NÃO INSPECIONADA

Inspection

Location	-
Auction Centre	Lisboa


Damage Assesment



Damage Detail : Pára-brisas_frente+capot

Damage Type : Picado


Damage Size : Ver Imagem



Damage Detail : Pára-choques_frente

Damage Type : Raspado


Damage Size : Ver Imagem



Damage Detail : Retrovisor

Damage Type : Raspado


Damage Size : Ver Imagem



Damage Detail : Pára-choques_traseiro

Damage Type : Raspado

Damage Size : Ver Imagem



Damage Detail : Jantes

Damage Type : Raspadas

Damage Size : Ver Imagem