




# CONDITION REPORT

2014 BMW Serie-5 LCI Diesel 520 d Pack M 190HP Saloon  
2014 | 136496 KM | Manual | Diesel | 190 hp  
Seller Disclosure



4

Grade  
Manheim

36-PG-37

Engine Size	1995 cm3
Seats	5
Number of Doors	4
Body Style	Saloon
Body Colour	Azul
HP	190 hp
VIN	WBA5E51010G100244
<b>Technical Inspection</b>	
DUA	Yes
Registration Date	19/11/2014
Last Service Date	Aos 132.330 kms em 27.03.2019 - digital

- ✓ 2ª CHAVE
- ✓ Service History
- ✓ VAT
- ✗ Sold as Seen



#### Condition Info

<b>Sold as Seen</b>	No
<b>Engine</b>	-
<b>Transmission</b>	-
<b>Suspension</b>	-
<b>Brakes</b>	-
<b>Clutch</b>	-
<b>Gearbox</b>	-
<b>Steering</b>	-

#### Equipment

XENON LAMPS  
ALLOY WHEELS  
PARKING AID  
SECOND KEYS  
SERVICE HISTORY  
AUTO AIRCON

#### Public Notes


VERIFIQUE PERITAGEM DENTRO DO  
ECR MANHEIM  
KIT ANTIFURO EM FALTA  
ULT REV Aos 132.330 kms em  
27.03.2019 - digital  
CUSTO AVERB 80€/  
DEMORA APROX 30  
VIATURA NÃO INSPECIONADA

#### Inspection

<b>Location</b>	-
<b>Auction Centre</b>	Lisboa

## Damage Assesment


---



**Damage Detail** : Para-brisas\_frente+capot

**Damage Type** : Picado


**Damage Size** : Ver Imagem



**Damage Detail** : Para-choques\_frente

**Damage Type** : Raspado


**Damage Size** : Ver Imagem



**Damage Detail** : Retrovisor

**Damage Type** : Raspado


**Damage Size** : Ver Imagem



**Damage Detail** : Para-choques\_traseiro

**Damage Type** : Raspado

**Damage Size** : Ver Imagem



**Damage Detail** : Jantes

**Damage Type** : Raspadas

**Damage Size** : Ver Imagem