



















36-PG-37

WBA5E51010G100244

2014 BMW Serie-5 LCI Diesel 520 d Pack M 190HP Saloon



Odometer	136496 KM	Fuel	Diesel	Body Colour	Azul
Transmission	Manual	Body Style	Saloon	Registration Date	11/19/2014 12:00:00 AM
Engine Size	1995 cm3	HP	190 hp	Number of Gears	
Seats	5	VAT	Refundable	Number of Keys	2
Service History	Aos 132.330 kms em 27.03.2019 - digital	Number of Doors	4	Euronorm	



Grade 4

Technical Inspection

DUA Yes

Equipment

XENON LAMPS
ALLOY WHEELS
PARKING AID
SECOND KEYS
SERVICE HISTORY
AUTO AIRCON

Tyres


Wheel	Condition	Type
Front Left	-	-
Front Right	-	-
Rear Left	-	-
Rear Right	-	-
Spare	-	-

Public Notes


VERIFIQUE PERITAGEM DENTRO DO ECR MANHEIM
KIT ANTIFURO EM FALTA
ULT REV Aos 132.330 kms em 27.03.2019 - digital
CUSTO AVERB 80€/
DEMORA APROX 30
VIATURA NÃO INSPECIONADA

Condition Info


Sold as Seen	No
Engine	-
Transmission	-
Suspension	-
Brakes	-
Clutch	-
Gearbox	-
Steering	-

Damage Assesment


Pára-brisas_frente+capot
Picado
Ver Imagem




Pára-choques_frente
Raspado
Ver Imagem



Retrovisor
Raspado
Ver Imagem



Pára-choques_traseiro
Raspado
Ver Imagem



Jantes
Raspadas
Ver Imagem

Inspection

Customer Ref	-	Location	-	Emissions Inspection Date	-	Technical Inspection	8/9/2019 12:00:00 AM
Movement No	-	Auction Centre	Lisboa	Control No	-	Lighting	-