



CONDITION REPORT

2019 Renault Clio IV Diesel Fase II 1.5 dCi Zen 75HP
Hatchback

2019 | 84919 KM | Manual | Diesel | 75 hp

3

Grade
Manheim

06-XP-55

Engine Size	1461 cm3
Seats	5
Number of Doors	5
Body Style	Hatchback
Body Colour	Cinzento
HP	75 hp
VIN	VF1R9800063202595

Technical Inspection

DUA	No
Registration Date	11/06/2019
Last Service Date	-



2ª CHAVE



Service History



VAT



Sold as Seen



 **MANHEIM**
Auction Services
COX AUTOMOTIVE



Condition Info

Sold as Seen	No
Engine	Good
Transmission	Good
Suspension	Good
Brakes	Good
Clutch	Good
Gearbox	Good
Steering	Good

Equipment

AC MANUAL
SECOND KEYS
SERVICE HISTORY

Public Notes

MANUAIS E 2ª CHAVE A ENTREGAR
PELA GESTORA DE FROTAS
MECÂNICA:
BATERIA FRACA NÃO CARREGA
CUSTO AVERBAMENTO 108€
APROXIMADAMENTE 45 DIAS
SEM DUA E IPO DISPONIVEIS NA
MANHEIM

Inspection

Location	Lisboa
Auction Centre	Lisboa

Damage Assesment



Damage Detail : Pára-choques_frente
Damage Type : Raspado
Damage Size : Ver Imagem



Damage Detail : Capot
Damage Type : Vincado
Damage Size : Ver Imagem



Damage Detail : Pára-choques_traseiro
Damage Type : Raspado
Damage Size : Ver Imagem



Damage Detail : Porta_detrás_direita
Damage Type : Mossas
Damage Size : Ver Imagem



Damage Detail : Farol_frente_direita
Damage Type : Raspado
Damage Size : Ver Imagem



Damage Detail : Banco
Damage Type : Queimado
Damage Size : Ver Imagem



Damage Detail : Habitáculo
Damage Type : Gasto
Damage Size : Ver Imagem