



CONDITION REPORT

2019 BMW X1 X1 1.5 SDRIVE16D 116HP

2019 | 99700 KM | Manuelle | Diesel | 116 hp

Seller Disclosure



8881LDC

Engine Size	1496 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	BLANCO
HP	116 hp
VIN	WBA31AC0105P42628
Technical Inspection	
DUA	No
Mise en circulation	12/12/2019
Last Service Date	-

- ✘ 2ª CHAVE
- ✘ CARNET D'ENTRETIEN
- ✔ VAT
- ✘ Vendus



Equipement

Notes publique

Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Emplacement** Madrid
Auction Centre Madrid **CALCULA TU TRANSPORTE**

Inspection

Emplacement Madrid
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-