



CONDITION REPORT

2018 BMW X1 X1 2.0 SDRIVE18D BUSINESS 150HP

2018 | 109422 KM | auto | Diesel | 150 hp

Seller Disclosure



7480KRV

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	BLANCO
HP	150 hp
VIN	WBAJH510103G29502
Technical Inspection	
DUA	No
Mise en circulation	27/11/2018
Last Service Date	-

- 2ª CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN (Informe Tecnico) PARA MÁS FOTOS + COMPROBAR POSIBLES DAÑOS + INFORMACIÓN ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-