



CONDITION REPORT

2019 OPEL COMBO COMBO 1.6 TD 74KW EXPRESS 650KG
S/S SWB 100HP

2019 | 40937 KM | Manuelle | Diesel | 100 hp

Seller Disclosure



2096LDB

Engine Size	1560 cm3
Places assises	-
Nombre de portes	3
Type de carrosserie	-
Couleur carrosserie	BLANCO
HP	100 hp
VIN	W0VEFYHYCLN500716
Technical Inspection	
DUA	No
Mise en circulation	05/12/2019
Last Service Date	-

- ✘ 2º CHAVE
- ✘ CARNET D'ENTRETIEN
- ✔ VAT
- ✘ Vendus



Equipement

Notes publique

Inspection

[CALCULA TU TRANSPORTE](https://www.manheimtransportatucoche.es/es/transportas/manheim)

Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid


Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-