



CONDITION REPORT

2020 BMW SERIE 1 SERIE 1 2.0 118D 150HP

2020 | 102013 KM | Manuelle | Diesel | 150 hp

Seller Disclosure



7370LLW

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	NEGRO GRIS METALIZ
HP	150 hp
VIN	WBA7M910X07H44623
Technical Inspection	
DUA	No
Mise en circulation	23/12/2020
Last Service Date	-

- ☒ 2ª CHAVE
- ☒ CARNET D'ENTRETIEN
- ☒ VAT
- ☒ Vendus



Equipement

Notes publique

Inspection


<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Emplacement -
Auction Centre Madrid


Inspection

Emplacement -
Auction Centre Madrid


Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -