



CONDITION REPORT

2019 Citroen BERLINGO (FURGON) BERLINGO (FURGON)
1,5 BLUEHDI 75KW S&S TALLA M DRI 75HP

2019 | 124367 KM | Manuelle | Diesel | 75 kw

Seller Disclosure



7690LCT

Engine Size	1499 cm3
Places assises	-
Nombre de portes	4
Type de carrosserie	-
Couleur carrosserie	GEN0002 - BLANCO
HP	75 kw
VIN	VR7EFYHYCKN561996
Technical Inspection	
DUA	No
Mise en circulation	27/11/2019
Last Service Date	-

- 2º CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN (Informe Técnico) PARA MÁS FOTOS + COMPROBAR POSIBLES DAÑOS + INFORMACIÓN ADICIONAL

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-