



CONDITION REPORT

2018 Nissan E-NV200 Nissan e-NV200 Furgón 5p 40 kWh
PREMIUM furgón 80k HP

2018 | 104417 KM | auto | electric |

Seller Disclosure



2746KPY

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	-
VIN	VSKYAAME0U0603228
Technical Inspection	
DUA	No
Mise en circulation	17/10/2018
Last Service Date	-

- 2ª CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Inspection

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-