



CONDITION REPORT

2021 TOYOTA PROACE PROACE 1.5D 100CV GX 1PL 2PT L1 HP

2021 | 86654 KM | Manuelle | Diesel |

Seller Disclosure



4530LSW

Engine Size	1499 cm3
Places assises	-
Nombre de portes	4
Type de carrosserie	-
Couleur carrosserie	- BLANCO ARCTIC
HP	-
VIN	YARVBYHRKGZ005057
Technical Inspection	
DUA	No
Mise en circulation	17/09/2021
Last Service Date	-

- 2º CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection

IMPORTANTE: VER PERITACIÓN (Informe Tecnico) PARA MÁS FOTOS + COMPROBAR POSIBLES DAÑOS + INFORMACIÓN ADICIONAL

Emplacement Madrid
Auction Centre Madrid

Inspection

Emplacement Madrid
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-