



CONDITION REPORT

2021 Renault Captur CAPTUR Zen TCe 67 kW (90CV) -SS HP

2021 | 63660 KM | Manuelle | Essence |

Seller Disclosure



4243LRZ

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	BIXNK - Carrocería Gris Casiopea con techo Negro
HP	-
VIN	VF1RJB00366827608
Technical Inspection	
DUA	No
Mise en circulation	22/07/2021
Last Service Date	-
2ª CHAVE	
CARNET D'ENTRETIEN	
VAT	
Vendus	




Equipement	Notes publique	Inspection
	RALU18-RSGALT-RDIF21-QPA\$XNK	Emplacement Auction Centre - Madrid

Inspection
Emplacement Auction Centre - Madrid

Damage Assesment



Détail du dommage : -
Type de dommage : -
Taille du dommage : -



Détail du dommage : -
Type de dommage : -
Taille du dommage : -