



CONDITION REPORT

2019 BMW X1 X1 SDRIVE18DA BUSINESS(CAM) 150HP

2019 | 148215 KM | Manuelle | Diesel | 150 hp

Seller Disclosure



3898KTN

Engine Size	1995 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	BLANCO
HP	150 hp
VIN	WBAJH51090EK97326
Technical Inspection	
DUA	No
Mise en circulation	13/02/2019
Last Service Date	-

- 2ª CHAVE
- CARNET D'ENTRETIEN
- VAT
- Vendus



Equipement

Notes publique

Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> **Emplacement** Madrid
Auction Centre Madrid

Inspection

Emplacement Madrid
Auction Centre Madrid

Damage Assesment



Détail du dommage :-

Type de dommage :-

Taille du dommage :-