



CONDITION REPORT

2019 Nissan E-NV200 Nissan e-NV200 Furgón 4p 40 kWh
PROFESIONAL furgón HP

2019 | 40007 KM | auto | electric |

Seller Disclosure



2182KTM

Engine Size	-
Places assises	-
Nombre de portes	-
Type de carrosserie	-
Couleur carrosserie	Blanco
HP	-
VIN	VSKHAAME0U0607358
Technical Inspection	
DUA	No
Mise en circulation	08/02/2019
Last Service Date	-



2º CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Emplacement	-
Auction Centre	Madrid

Inspection

Emplacement	-
Auction Centre	Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-