



# CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON (O)1.6 CRDI 85KW 48V SLE 2WD 116HP

2020 | 149742 KM | Manuelle | Diesel | 116 hp

Seller Disclosure



## 9313LGK

Engine Size	1598 cm3
Places assises	-
Nombre de portes	5
Type de carrosserie	-
Couleur carrosserie	MICRON GREY
HP	116 hp
VIN	TMAJ3817ALJ980915
<b>Technical Inspection</b>	
DUA	No
Mise en circulation	22/05/2020
Last Service Date	-

- ✘ 2<sup>o</sup> CHAVE
- ✘ CARNET D'ENTRETIEN
- ✔ VAT
- ✘ Vendus



### Equipement

### Notes publique

### Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> - CALCULA TU TRANSPORTE


**Emplacement** -  
Auction Centre Madrid

### Inspection

**Emplacement** -  
**Auction Centre** Madrid

## Damage Assesment

---



Détail du dommage :-

Type de dommage :-

Taille du dommage :-