



CONDITION REPORT

2019 Nissan E-NV200 Furgón 4p 40 kWh PROFESIONAL
furgón 80KW (109CV) 4 HP

2019 | 34855 KM | auto | electric |

Seller Disclosure



3832KTG

| | |
|-----------------------------|-------------------|
| Engine Size | - |
| Places assises | - |
| Nombre de portes | - |
| Type de carrosserie | - |
| Couleur carrosserie | Blanco |
| HP | - |
| VIN | VSKHAAME0U0606803 |
| Technical Inspection | |
| DUA | No |
| Mise en circulation | 30/01/2019 |
| Last Service Date | - |



2ª CHAVE



CARNET D'ENTRETIEN



VAT



Vendus



Equipement

Notes publique

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA MÁS FOTOS +
COMPROBAR POSIBLES DAÑOS +
INFORMACIÓN ADICIONAL

Inspection

Emplacement -
Auction Centre Madrid

Inspection

Emplacement -
Auction Centre Madrid

Damage Assesment



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-



Détail du dommage :-
Type de dommage :-
Taille du dommage :-